

Annexure D

BUILDING SAFETY CERTIFICATE

No.109..... 1-1-6A

Dated ...25.06.2026

It is certified that the existing building **Carmel Public School** at **Nawada Road Gajraula, Amroha** is having block(s)/floor(s) as per details below -

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	01 No. Ground, First and Second floor	01 No. Ground, First and Second floor	01 No. Ground, First and Second floor	-	-	-

The building is owned/occupied by **Carmel Public School** have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **PWD on 25-06-2026** (date of inspection) in the presence of **Principal / Manager** of and that the building/premises is fit for occupancy for running school with effect from **25-06-2026** for a period of **03 Years** in accordance with rule and subject to compliance of the specific conditions as appended.

1. Continuous Monthly maintenance of building during above period.
2. Continuous Cleaning of rain water pipes and roof & top before rains.
3. During above Period if any cracks seen in building, information to be given to department for further inspection for instruction.

Issued on :- **25-06-2026**


Signature with Seal:

Name:

Designation :


Name and Address

of Department/office :


Ranveer singh
Assistant Engineer
Provincial Division

P.W.D. Amroha
(रनवीर सिंह)

सहायक अभियन्ता
प्रान्तीय खण्ड, लो०नि०वि०
अमरोहा



Manager
Carmel Public School
Gajraula