

Annexure D

BUILDING SAFETY CERTIFICATE

No. 20

Dated: 8/8/25

Certified that the existing building St. Mary's School, Bhikkawala, Shanti Nagar, Afzalghar Teh-Dhampur Distt- Bijnor (U.P.) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Ground+02	Ground+01	-	-	-	-

The building is owned/occupied by St. Mary's School, Bhikkawala, Shanti Nagar, Afzalghar Teh-Dhampur Distt- Bijnor (U.P.) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Assistant Engineer, Rural Engineering Department, Bijnor on 04-08-2025 in the presence of Fr. Philip Karickaunnel (Manager) and that the building/premises is fit for occupancy for running school with effect from 04-08-2025 for a period of 03 years in accordance. with rule and subject to compliance of the specific conditions as appended.

- 1- Building is in earthquake Zone-4, so it should be regularly maintained and inspected. Department will not be responsible for any adverse situation in future.
- 2- Annexure-'B'-From for first application to develop, erect, re-erect or to make alteration In any place in a building - Duly signed by manager of school. Reg. No.- 08/BRA
- 3- Annexure-'C'-From for certificate for structural design sufficiency - Duly signed by manager of school. Reg. No.- 08/BRA
- 4- Annexure-'D'-From for supervision-Duly signed by manager of school. Reg. No.- 08/BRA
- 5- Annexure-'G'-From for certificate for execution of work as per structural safety requirements Duly signed by manager of school.
- 6- Annexure-'H'-From for completion certificate - Duly signed by Principal of school.
- 7- In future, if building construction found any discrepancy from specification of NBC-2016, the Rural Engineering Department will not be responsible for that.

Issued on 04-08-2025 at Vikas Bawan, Bijnor by Bhanu Rana, Asst Engineer, Rural Engineering Department Bijnor.

*Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Digitally signed by
BHANU RANA

Date: 08-08-2025

17:05:28

Signature with Seal:

Name: Bhanu Rana

Designation: Asst. Engineer

Name & Address of Department/ Office: Rural Engineering Department

Vikas Bhawan Bijnor.

प्रेषक,

सहायक अभियन्ता,
ग्रामीण अभियन्त्रण विभाग,
प्रखण्ड-बिजनौर।

सेवा में,

प्रबन्धक,
सेंट मेरीस स्कूल, भिकवावाला
शान्ति नगर, अफजलगढ़ तहसील धामपुर
जिला-बिजनौर।

पत्रांक 20 / ग्रा0अ0वि0/अनापत्ति प्रमाण-पत्र/2025-26

दिनांक 8/8/25

सन्दर्भ :- आपका पत्र दिनांक-10.06.2025

विषय:- सेंट मेरीस स्कूल, भिकवावाला, शान्ति नगर, अफजलगढ़ तहसील धामपुर, जिला-बिजनौर के लिए नेशनल बिल्डिंग कोड अननपत्ति प्रमाण-पत्र के सम्बन्ध में।

महोदय,

उपरोक्त विषयक सन्दर्भित पत्र के क्रम में अधोहस्ताक्षरी द्वारा सेंट मेरीस स्कूल, भिकवावाला, शान्ति नगर, अफजलगढ़ तहसील धामपुर, जिला-बिजनौर के विद्यालय भवन का स्थलीय निरीक्षण किया गया। स्थलीय निरीक्षण में अवगत कराया गया भवन में दो ब्लॉक हैं। प्रथम ब्लॉक G+2 स्तर तक निर्मित है तथा द्वितीय ब्लॉक G+1 स्तर तक निर्मित है। प्रबन्धक द्वारा प्रस्तुत भवन मानचित्र के अनुसार प्रथम ब्लॉक के भूतल पर कवर्ड क्षेत्रफल 767.00 (वर्ग मीटर), प्रथम तल पर कवर्ड क्षेत्रफल 687.00 (वर्ग मीटर) तथा द्वितीय तल पर कवर्ड क्षेत्रफल 662.00 (वर्ग मीटर) है। दूसरे ब्लॉक में भूतल एवं प्रथम तल पर कवर्ड क्षेत्रफल 671.00 (वर्ग मीटर) है। प्रथम दृष्ट्या भवन के सभी कक्षा-कक्षों की दीवार व छतों में पूर्ण मजबूती प्रतीत होती है और भवन में धूप व ठण्ड के बचाव की पर्याप्त व्यवस्था की गयी है। भवन में बने लगभग सभी कक्षा-कक्ष हवादार एवं रोशनीयुक्त हैं।

1-Annexure-'B'- Form for first application to develop, erect, re-erect or to make alteration in any place in a building-Duly signed by Manager of school And Structural Engineer Certificate No.-Er.Pankaj Kumar Sharma Architecture Designer Reg. No.-08/BRA

2-Certificate for structural design sufficiency - Duly signed by Structural Engineere Reg. No.- 08/BRA

3-Annexure-'E'- Form for Supervision - Duly signed by manager of school . And Structural Engineere Reg. No.- 08/BRA

4-Annexure-'G'- Form for certificate for execution of work as per structural safety requirements Duly signed by manager of school And Structural Engineere Reg. No.- 08/BRA

5-Annexure-'H'- Form For completion certificate - Duly signed by manager of school And Structural Engineer Reg. No.- 08/BRA

Annexure-'C' & Annexure-'D' में प्रमाणित किया गया है कि उक्त भवन नेशनल बिल्डिंग कोड-2016 के मानक के अनुसार निर्माण कराया। प्रथम दृष्ट्या उपरोक्त विद्यालय का निर्माण एन0बी0सी0-2016 के अनुसार प्रतीत होता है। अगर भविष्य में विस्तृत जांच उपरान्त विद्यालय भवन का निर्माण एन0बी0सी0-2016 के अनुसार विशिष्टियों से भिन्न पाया जाता है तो उपरोक्त में ग्रामीण अभियन्त्रण विभाग प्रखण्ड-बिजनौर की कोई जिम्मेदारी नहीं होगी। अतः जोन-4 में होने के कारण उक्त भवन की तकनीकी जांच समय-समय पर होनी अनिवार्य है।

अतः उपरोक्त शर्तों एवं दिये गये प्रमाण पत्रों के आधार पर नेशनल बिल्डिंग कोड के सुरक्षा सम्बन्धी अनापत्ति प्रमाण पत्र निर्गत किया जाता है।

Digitally signed by

BHANU RANA

Date: 08-08-2025

17:04:43 (मानु राना)

सहायक अभियन्ता
ग्रामीण अभियन्त्रण विभाग
प्रखण्ड-बिजनौर।

पत्रांक एवं दिनांक उपरोक्तानुसार।

प्रतिलिपि:- मुख्य विकास अधिकारी, जिला-बिजनौर की सेवा में सूचनार्थ प्रेषित।

सहायक अभियन्ता
ग्रामीण अभियन्त्रण विभाग
प्रखण्ड-बिजनौर।